



DWA-547 A3 RangeBooster N 650 Desktop Adapter Firmware

Release Notes

Firmware: v1.71b09 (WW)

Hardware: A3

Date: 2013/May/27

Driver:

Win8 Driver version : v10.0.0.209

Win8 WlanDll version : v1.45.132.60

Win8 WlanWPS version : v1.0.9.112(JSW version: v2.1.0.18)

Win7 Driver version : v9.2.0.512

Win7 WlanDll version : v1.45.132.60

Win7 WlanWPS version : v1.0.9.112(JSW version: v2.1.0.18)

Vista Driver version : v7.7.0.498

Vista WlanDll version : v1.45.132.60

Vista WlanWPS version : v1.0.9.112(JSW version: v2.1.0.18)

2KXP Driver version : v9.2.0.512

2KXP WlanDll version : v1.29.132.50

2KXP WlanWPS version : v1.0.9.112(JSW version: v2.1.0.18)

Problems Resolved:

1. Fix the low Signal Strength Show in Utility
2. Win8 OS support

Known issue:

NA
